

ਦਫਤਰ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

Email ID: eecdmuksarpwdpb@ gmail. com

ਵੱਲ,

ਪ੍ਰਿੰਸੀਪਲ,
ਭਾਈ ਮਸਤਾਨ ਸਿੰਘ, ਪਬਲਿਕ ਸਕੂਲ,
ਸੀਨੀ. ਮੈਕਡਰੀ ਸਕੂਲ, ਮਲੋਟ ਰੋਡ,
ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

ਨੰਬਰ: 1379

ਮਿਤੀ: 29-5-24


ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਲੈਣ ਬਾਰੇ। ਸਾਲ 2024-25 (Bhai Mastan Singh, Public Sec. Sec. School, Malout Road, Sri Muktsar Sahib.

ਹਵਾਲਾ:- ਆਪ ਦਾ ਬਿਨੇ-ਪੱਤਰ Bmsps/12855/2024 ਮਿਤੀ 08-05-2024

ਆਪ ਦੇ ਸਕੂਲ ਦਾ ਨਿਰੀਖਣ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ ਵੱਲੋਂ ਕਰ ਲਿਆ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾਂ ਦੀ ਰਿਪੋਰਟ ਦੇ ਆਧਾਰ ਤੇ ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇਖਣ ਤੋਂ ਠੀਕ ਹੈ ਅਤੇ ਵਰਤਣਯੋਗ ਹੈ। ਇਸ ਲਈ ਆਪ ਨੂੰ ਹੇਠ ਲਿਖੀਆਂ ਸਰਤਾਂ ਦੇ ਆਧਾਰ ਤੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦੇ ਸਿਵਲ ਵਰਕ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਸਾਲ 2024-25 (31 ਮਾਰਚ 2025) ਜਾਰੀ ਕੀਤਾ ਜਾਦਾ ਹੈ :-

1. ਇਸ ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਸਾਲ ਮੁਰੰਮਤ ਕਰਵਾਈ ਜਾਵੇ।
2. ਇਸ ਬਿਲਡਿੰਗ ਦੀਆਂ ਛੱਤਾਂ ਉੱਪਰ ਅਤੇ ਆਲੇ ਦੁਆਲੇ ਪਾਣੀ ਨਾ ਖੜਾ ਹੋਣ ਦਿੱਤਾ ਜਾਵੇ।
3. ਜੇਕਰ ਬਿਲਡਿੰਗ ਵਿੱਚ ਕਿਸੇ ਤਰ੍ਹਾਂ ਦੀ ਤਰੇਤ ਆ ਜਾਂਦੀ ਹੈ ਤਾਂ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਨਾ ਲਿਆਂਦਾ ਜਾਵੇ ਅਤੇ ਉਸ ਜਗ੍ਹਾ ਨੂੰ ਤੁਰੰਤ ਖਾਲੀ ਕਰਵਾ ਕੇ ਜਗ੍ਹਾ ਦੀ ਤੁਰੰਤ ਮੁਰੰਮਤ ਕਰਵਾਈ ਜਾਵੇ।
4. ਬਿਲਡਿੰਗ ਦੀ ਹਰ ਪੱਖੋਂ ਸੇਫਟੀ ਦੀ ਜਿੰਮੇਵਾਰੀ ਸੰਸਥਾ ਦੀ ਹੋਵੇਗੀ। ਅੱਗ ਬੁਝਾਊ ਯੰਤਰ ਚਾਲੂ ਹਾਲਤ ਵਿੱਚ ਹੋਣੇ ਚਾਹੀਦੇ ਹਨ।
5. ਜੇਕਰ ਕਿਸੇ ਕੁਦਰਤੀ ਆਫਤ ਕਾਰਨ ਜਾਂ ਕਿਸੇ ਵੀ ਕਾਰਨ ਬਿਲਡਿੰਗ ਦਾ ਨੁਕਸਾਨ ਹੁੰਦਾ ਹੈ ਤਾਂ ਤੁਰੰਤ ਇਸ ਦਫਤਰ ਨੂੰ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ।
6. ਜੇਕਰ ਬਿਲਡਿੰਗ ਵਿੱਚ ਕਿਸੇ ਤਰ੍ਹਾਂ ਦਾ ਵਾਧਾ ਕਰਨਾ ਹੋਵੇ ਤਾਂ ਆਰਕੀਟੈਕਟ ਤੋਂ ਪਾਸ ਕਰਵਾਇਆ ਜਾਵੇ ਅਤੇ ਇਸ ਸਬੰਧੀ ਇਸ ਦਫਤਰ ਨੂੰ ਵੀ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ।
7. ਸਕੂਲ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 27-07-2024 ਨੂੰ ਖਤਮ ਹੋਣਾ ਹੈ। ਸਕੂਲ ਇਸ ਤੋਂ ਬਾਅਦ ਮਿਤੀ 31-03-2025 ਤੱਕ ਦਾ ਫਾਇਰ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸ ਜਮ੍ਹਾਂ ਕਰਵਾਉਣ ਲਈ ਪਾਬੰਦ ਹੋਵੇਗਾ, ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਇਸ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਸਮਝਿਆ ਜਾਵੇਗਾ।
8. ਜੇਕਰ ਭਵਿੱਖ ਵਿੱਚ ਪੰਜਾਬ ਸਰਕਾਰ ਵੱਲੋਂ ਕੋਈ ਵੀ ਰੋਡ ਅਸੈਸ ਜਾਂ ਕੋਈ ਹੋਰ ਫੀਸ ਪ੍ਰਾਪਤ ਕਰਨ ਲਈ ਹਦਾਇਤਾਂ ਪ੍ਰਾਪਤ ਹੁੰਦੀਆਂ ਹਨ ਤਾਂ ਉਹ ਫੀਸ ਆਪ ਦਾ ਸਕੂਲ ਭਰਨ ਲਈ ਪਾਬੰਦ ਹੋਵੇਗਾ। ਅਜਿਹਾ ਨਾ ਕਰਨ ਦੀ ਸੂਰਤ ਵਿੱਚ ਆਪ ਨੂੰ ਬਿਨਾਂ ਕੋਈ ਨੋਟਿਸ ਦਿੱਤੇ ਜਾਰੀ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਰੱਦ ਕੀਤਾ ਜਾ ਸਕਦਾ ਹੈ।

ਨੰਬੀ/ ਸਰਟੀਫਿਕੇਟ


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

ਮਿਤੀ:

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰਬਰ: 97 ਮਿਤੀ: 17-05-2024 ਦੇ ਹਵਾਲੇ ਵਿੱਚ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਸ੍ਰੀ ਮੁਕਤਸਰ ਸਾਹਿਬ।

PERFORMA FOR THE SAFETY OF SCHOOL BUILDING

Part-I

(To be filled by the Head School/Institute)

1. Name of the School : BHAJ MASTAN SINGH PUBLIC SCHOOL
2. Location : Malout Road, Sri Muktsar Sahib
3. Plot area: 416273 Sq ft. (38445.13 Sq meter) or 76 Kanals, 9 Marlas
4. Plinth area: 113542 Sq ft.
5. No. of Storeys: Block No.1-3 Storey. Block No. 2-3 Storey
6. Year of construction of building: Block No.1- 2002-2003, Block No. 2-2016-17
3rd Storey 2019-20
4th Storey 2023-24
7. If the Building has been constructed under the supervision
Of the qualified Engineer, the following details may be given: Yes
 - (a) Name of the Engineer with qualification: Er. Amandeep Singh
 - (b) Address of the Engineer: Ar. Jagpreet Chhabra
 - (c) Set of structural drawings used in: Jodhu Colony, City Hotel Road, Mkt
 - (d) Name and address of Architect with Qualifications: Certificate attached here with
Roof Architects,
(CD-Architecture)
Sri Muktsar Sahib
8. Whether the building has been constructed for the purpose of
 - a. School Yes
 - b. Residential purpose and converted
For use as a school
9. Material used for roofs:
 - a. R.C.C. Slabs Yes
 - b. R.S. Joists & battons No
 - c. Wooden joints and battons No
 - d. Jail Arch Roofing No
10. Material used for walls:
 - a. Mud Mortar No
 - b. Cement Motor Yes
 - c. Plaster i) Lime Mortor ii) Cement Mortar (i) No (ii) Yes
11. Loorings:
 - a. Chglomerate Yes
 - b. Terranze Yes
 - c. Brick Paving No
12. A detailed drawing indicating dimensions
Of the rooms along with size and location of
Doors and windows (attached). Attached

(Part-II)


- I have visited the above mentioned school on 17-5-2024 and have visually inspected it from all angles of safety and find it for normal use as me school Building.
- In case any addition/ alteration or expansion and modification to these buildings is to be carried out, the same be carried out under that revision of a technically qualified. Engineer and this certificate may again be obtained after the completion form the undersigned.
- In case the building is effected by flood, or there is section of with conditions or sagging of roofs etc. immediately inspection of the undersigned be arranged to check the sterility and safety or the building.


(Bhai Mastan Singh Public School, Sri Muktsar Sahib)

This building can be safety occupied for normal use up to (Inufary or to which it can be used) 31-3-2025

This Building seems
to be safe in normal
Climate condition
Sahil

CS


Sub-Divisional Engineer
Provl. Sub Divn. PWD B&R Br.
Sri Muktsar Sahib
PWD & R Branch _____
S


Executive Engineer,
Construction Div. PWD
B&R Shri Muktsar Sahib
S